



Amp Draw Chart

Fan Speed

Amp Draw

100% = 2.66a

90% = 1.90a

80% = 1.56a

70% = 1.23a

60% = 0.95a

50% = 0.70a

40% = 0.48a

30% = 0.33a

20% = 0.21a

10% = 0.15a